


FIG. 2



ProOpsContainer - [SCM_FIT_1]Monitor

File Window Edit Help

8

+

-

SCM_FIT_1

STEP_One Q

STEP_Two

STEP_Three

Confirm

Info

Info

Info

Conf Instruction

Step: STEP_One: 2 auto, 1 info, 1 conf

Set CM_FIT Pid ModeAttr to Program

Set CM_FIT Pid Mode to Auto

Info Instruction

Conf Instruction

44.3872

PROGR

AUTO p

string va

312

Conf Instruction with both

1. Warning

2. Note

MAIN

Warning

Note

Instruction

Target: string value #1

Current: string value #2

Entry: string value #3

Warning for Output #4

Ready

FIG. 4

108

106

ProOpsContainer - [SCM_FIT_1 [Monitor]]

File Window Edit Help

SCM_FIT_1

STEP_One

STEP_Two

STEP_Three

Confirm

Info

Conf

Conf

Step: STEP_One: 1 info, 2 conf, enforce seq

Info Instruction

Conf Instruction; no param refs

Conf Instruction; entry ref only, no warning/note

44

True

Task

501

502

500

Instruction for Output #3

Instruction

Instruction for Output #3

Entry: NaN

Ready

FIG. 5

ProOpsContainer - [SCM_FIT_1] [Monitor]

File Window Edit Help

+

-

Confirm	Description	Current	Task
<input type="checkbox"/>	Step: STEP Three: 0/1 Instr/Expr: 1/0: 0/0		
<input type="checkbox"/>	No Instr and Auto expr		
<input type="checkbox"/>	Conf Instr and No Auto expr		
Info	Both Info Instr and Auto expr		
Info	Blank Info Instr and No Auto expr		


STEP MAIN

Ready

600

602

FIG. 6

**FIG. 7**




FIG. 8